Y:\0000\CADD STANDARDS\DETAILS\City Details\Easton MD\DETAILS\PW-1.07.dwg Dec 22 , 2010 - 2:10pm, (batn)



LONGITUDINAL PAVEMENT REPAIR

NOTE:
1. SEE DETAIL PW-1.06 FOR TRENCH RESTORATION.
2. SURFACE RESTORATION ON LONGITUDINAL TRENCHES SHALL INCLUDE MILL AND OVERLAY FOR 1 FULL LANE WIDTH FOR 15' BEYOND EITHER SIDE OF THE EXCAVATION.

APPROVAL

TOWN ENGINEER — DATE

REVISED
OCT 11, 10
JAN 1, 11

ISSUED: FEB 25, 2009

TOWN OF EASTON
AND
EASTON UTILITIES
STANDARD DETAILS

PAVEMENT
RESTORATION DETAIL #1

STANDARD NO. PW-1.07